



Report

Glass unit Id:	42000
Quality level:	1
Operator:	1
Processed date:	2022-07-26 22:04:21
Inspection date:	-
Defect count:	4
Length (mm):	2140
Height (mm):	419
Barcode:	-
Custom field 1:	-
Custom field 2:	-
Custom field 3:	-
Custom field 4:	-


Backlight image




Dark field image



Reflex image




Infrared image




Defectos

Defect Id: 1
Area: 2207
Contrast: 86
Length: 67
Width: 338
Height: 221
Type: 1




Defect Id: 2
Area: 914.5
Contrast: 129
Length: 34
Width: 170
Height: 64
Type: 1



Defects

Defect Id: 3
Area: 110
Contrast: 95
Length: 3
Width: 10
Height: 16
Type: 1



Defect Id: 4
Area: 100.5
Contrast: 236
Length: 2
Width: 13
Height: 11
Type: 1

